Measurements	°C
Sp1	13.5
Sp2	13.2
Sp3	11.7
Sp4	12.1
Sp5	11.8

Parameters	
Emissivity	0.95
Refl. temp.	20 °C

LOCATION: Mutual Stair well


Dampness in the hard plaster on the walls. Note the dampness in behind the wiring of the hall light. This could prove to be a Fire Hazard!

19/06/2015 18:07:40



FLIR0138.jpg FLIR C2 720004025

19/06/2015 15:08:24



IMG_2833.JPG